


**Description:**

Connect any MT8000/6000 series HMI via an isolated RS422 network to any RS232 ports using two FA-ISOCOCON isolated converters.



**Notes:**

1. For the network cables we recommend you use a two twisted-pair 22 or 24 AWG stranded, foil and braid shielded cable  
Eg: Belden 8133.
2. Separate substantial equi-potential earth wires should be run alongside screened cables to interlink earth points of control cubicles to eliminate fault currents between devices.

					Lamonde Automation own the copyright of this drawing which is supplied in confidence and which must not be reproduced or used for any purpose other than for which it is supplied	
REV.	DESCRIPTION	DATE	BY	CHKD		
<b>Title: MT8000/6000 series HMI to RS422 network via FA-ISOCOCON isolated converters</b>					<b>DRAWN BY</b>	<b>MLD</b>
					<b>DATE</b>	<b>19/10/2008</b>
					<b>SCALE</b>	<b>not to scale</b>
<b>Lamonde Automation Ltd.</b> Project House, Morris Road, South Nutfield, Surrey. RH1 5SA Tel: 01737 824600					<b>Part Number:</b> <b>MT8-FAISOCOCON</b>	